Installation Guide for Intel Socket 2011

1) Components: 1 Set of Clip Support (2EA), Nipple (4EA), Nut (4EA), Bolt (2EA)

2) Installation Steps



❶ Mount the Nipple, Clip Support, and Nut in the order shown in the diagram above.



❷ When mounting the Clip Support, note the mounting direction as shown in the diagram above.



❸ Apply thermal grease on the CPU.



❹ Place the ZM-WB5, ZM-WB5 PLUS on the center of CPU and fasten with the bolts provided.